

The Best Way to Clean Copper

FROM AHNA @ HAMMERSNHUGS.COM



COPPER CLEANING KIT LIST:

- [SALT](#)
- [WHITE VINEGAR](#)
- [HEAVY DUTY SPONGES](#)
- [BUFFING CLOTH](#)

DIRECTIONS:

1. POUR THE VINEGAR OVER THE COPPER.
2. SPRINKLE THE SALT OVER THE VINEGAR SIMULTANEOUSLY.
3. RUB THE MIXTURE ALL OVER THE COPPER AND LET SIT FOR 5-10 MINUTES.
4. SCRUB THE COPPER.
5. WASH WITH SOAP AND WATER.
6. BUFF AS DESIRED WITH CLOTH.